

## **PRODUCT DISCONTINUATION NOTICE**

PDN No.: USA2013/009

IXYS PRODUCT TYPE: IXFH14N100	<b>TYPE:</b> HIPL MOSFET	•	<b>MMEND REPLACEMENT:</b> FH12N100P
REASON FOR DISCONTINUAT	ION: LOW DEMAND, LACK	OF RAW MATERIALS	
LAST TIME ORDER DATE:	DECEMBER 31, 2013		
LAST TIME DELIVERY DATE:	DECEMBER 31, 2013		
INTERNAL REFERENCE: N/A	ı		
INITIATOR: GORDON ROSETE	TITLE/FUNCTION DEPT. HEAD QUALITY ASSURANCE	DATE AUGUST 23, 2013	E-MAIL G.ROSETE@IXYS.NET
CUSTOMER RESPONSE:			
(PLEASE FILL IN AND RETURN BY E-M	MAIL, FAX OR MAIL WITHIN 4 WEEKS)		
for further questions/ ir	nformation Com <sub> </sub>	pany:	
please comment		Name & Position	
COMMENTO	Phon	e / Fax No:	
COMMENTS:			
IF 0266 Rev.0 (01.26.1	0) Page	e 1 of 1	Reference QS 0073