

Material Change Notice

| CUSTOMER | CUSTOMER DRAWING NUMBER | | REV. NO. | TODAYS DATE |
|-----------------------|-----------------------------|--------|-------------------------|-------------|
| | Please see below | | | 5/27/2014 |
| CUSTOMER CONTACT NAME | TITLE | | PHONE NO./EXT | |
| JKL PART NUMBER | PART DESCRIPTION | | FAX NO. | |
| | | | | |
| various see below | NDL Series "EL Inverters" | | | |
| JKL CONTACT NAME | PHONE | EMAIL: | | |
| Sherry Carpenter | erry Carpenter 818-896-0019 | | scarpenter@jkllamps.com | |

Change Detail:

The inverters supplied contain a black epoxy resin fill (Somar Corp K-880NL) however, this material has gone obsolete. Newly produced inverters will contain a silicone rubber fill that meets and exceeds the performance of the former epoxy material. The new silicone rubber fill (Shi-etsu KE1204) is a red-brown color. As the JKL specification and product performance is unchanged, JKL will retain the same Part Number and Revision number. Inventory will be traceable per lot numbers.

New fill is red-brown color as shown. Old fill is black.



Items Affected by Change:

| Digi-key PN | JKL PN |
|-------------|---------|
| 289-1028-ND | NDL-201 |
| 289-1029-ND | NDL-202 |
| 289-1031-ND | NDL-204 |
| 289-1032-ND | NDL-205 |
| 289-1033-ND | NDL-217 |
| 289-1125-ND | NDL-212 |
| 289-1126-ND | NDL-210 |
| 289-1127-ND | NDL-208 |
| 289-1129-ND | NDL-106 |
| 289-1130-ND | NDL-203 |
| 289-1131-ND | NDL-102 |