

## **Global Change Notification (GCN)**

Product Family	Mini-fit	10719901	
		GCN Number	
Series	5559, 36667, 36764, 46993, 68801	October 20, 2015	
		Date Issued	
Reason For Change	New, Modified, Or Replacement Tooling		
Change Description	The letter is being sent to inform you that Molex is building a new mold to make 5559-14 housings in Lincoln.		
Series image - Reference only			
Part Numbers Affected	Please refer to CustomerPartList.csv attached to	e-mail message.	
Reason For Short Notice Exception			
Assessment Of Change (How Product Will Be Qualified & Validated)	There will be no change to the parts as a result complete the Molex internal qualification/approv to production.		
Internal Molex Qualification Date (Planned Date Information Available)	January 04, 2016		
Sample Availability Date (Changed Part)	January 04, 2016		
Date of Implementation	April 21, 2016		
Method of Identifying Change	Product made after March 31, 2016 can be from	the new mold.	
Recommended Replacement Parts	Not Applicable		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com